
From: Jeffrey R Marcell (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=JEFF136]
Sent: 1/20/2015 12:57:54 PM
To: Michael J Winters (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=MIC1082]
CC: John Cima (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=John171]; Jeffrey C Heffelman (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Jeffre3]; Kenneth Roller (Services - 6) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Kenne64]
Subject: RE: Ash Pond ABC inspection 01/20/15
Attachments: 20150120125617811.pdf

Attached.

No discharge at C Pond. No standing water around the weir.

Note: water was observed seeping into weir, not sure if this was moisture on the walls left over from the storm event yesterday or actual seeping, very slow rate. It has slightly increased compared to last week's inspection.

Total rainfall amount up to the time of inspection was roughly 0.42".

Let me know if you have any questions.

Jeff Marcell

Environmental Supervisor

Possum Point Power Station

Ladysmith & Remington CT Sites

703-441-3813 (phone)

8-795-3813 (tie)

703-441-3897 (fax)

